

**County of Santa Clara**  
**Department of Environmental Health**  
**Consumer Protection Division**

1555 Berger Drive, Suite 300, San Jose, CA 95112-2716  
 Phone (408) 918-3400 www.ehinfo.org



**OFFICIAL INSPECTION REPORT**

<b>Facility</b> FA0213262 - THE MEAT CORNER		<b>Site Address</b> 1036 E EL CAMINO REAL, SUNNYVALE, CA 94087	<b>Inspection Date</b> 03/22/2024
<b>Program</b> PR0304647 - NO FOOD PREP (GROCERY STORE) < 5,000 SQ FT - FP06		<b>Owner Name</b> SASWATA BHATTA CHARYA	<b>Inspection Time</b> 16:05 - 16:40
<b>Inspected By</b> SUKHREET KAUR	<b>Inspection Type</b> FOLLOW-UP INSPECTION	<b>Consent By</b> SASWATA	

<b>Placard Color &amp; Score</b> <b>GREEN</b> <b>N/A</b>
--

**Comments and Observations**

**Major Violations**

Cited On: 03/22/2024

K22 - 8 Points - Sewage and wastewater improperly disposed; 114197

**Inspector Observations: Three compartment sink is not draining into approved plumbing and water is leaking on the floor into a drain. [CA] Food facility shall not operate if there is sewage overflowing or backing up in the food facility. The food facility, or impacted areas, shall remain closed until all plumbing problems have been corrected and all contaminated surfaces have been cleaned and sanitized.**

Cited On: 03/22/2024

K22 - 8 Points - Sewage and wastewater improperly disposed; 114197

**Compliance of this violation has been verified on: 03/22/2024**

**Minor Violations**

Cited On: 03/13/2024

K41 - 2 Points - Plumbing unapproved, not installed, not in good repair; improper backflow devices; 114171, 114189.1, 114190, 114192, 114193, 114193.1, 114199, 114201, 114269

**This violation found not in compliance on 03/22/2024. See details below.**

Cited On: 03/22/2024

K41 - 2 Points - Plumbing unapproved, not installed, not in good repair; improper backflow devices; 114171, 114189.1, 114190, 114192, 114193, 114193.1, 114199, 114201, 114269

**Inspector Observations: Observed drops of water still leaking, however wastewater is properly disposing through approved plumbing.**

**[CA] Repair the plumbing fixture and maintain in good condition.**

**Measured Observations**

N/A

**Overall Comments:**

**On site for 2nd follow up inspection.**

**Per PIC, plumber was able to fix the issue that caused wastewater backup.**

**Water was kept running for about one minute at three compartment sink. Observed some drops of water leaking, however wastewater is disposing properly.**

**Facility is re-opened.**

**This is a charged inspection.**

When required to determine compliance, a single reinspection will be conducted without additional charge. If subsequent reinspections are required, an hourly fee (minimum one hour) at the current rate approved by the Board of Supervisors will be assessed for each and every reinspection until the necessary changes or corrections are made. Unless otherwise noted by the inspector, all violations are to be corrected no later than **4/5/2024**. Any major change in menu or any change in ownership must have prior approval by this Department. This may require structural and/or equipment changes or remodeling to accommodate new operations.

# OFFICIAL INSPECTION REPORT

<b>Facility</b> FA0213262 - THE MEAT CORNER	<b>Site Address</b> 1036 E EL CAMINO REAL, SUNNYVALE, CA 94087	<b>Inspection Date</b> 03/22/2024
<b>Program</b> PR0304647 - NO FOOD PREP (GROCERY STORE) < 5,000 SQ FT - FP06	<b>Owner Name</b> SASWATA BHATTA CHARYA	<b>Inspection Time</b> 16:05 - 16:40

**Legend:**

- [CA] Corrective Action
- [COS] Corrected on Site
- [N] Needs Improvement
- [NA] Not Applicable
- [NO] Not Observed
- [PBI] Performance-based Inspection
- [PHF] Potentially Hazardous Food
- [PIC] Person in Charge
- [PPM] Part per Million
- [S] Satisfactory
- [SA] Suitable Alternative
- [TPHC] Time as a Public Health Control



---

**Received By:** Saswata B  
Owner

**Signed On:** March 22, 2024